

COMBINACIÓN DE PIEZAS

CIERRES	UÑAS
C-2 ZINC C-2 C-12 ZINC C-12	U-2 ZINC U-2 U-6 ZINC U-6 U-7 ZINC U-7
C-3 ZINC C-3 C-13 ZINC C-13	U-3 ZINC U-3 U-9 ZINC U-9
C-4 ZINC C-4 C-14 ZINC C-14 C-5 ZINC C-5	U-4 ZINC U-4
C-7 ZINC C-7	U-2 ZINC U-2 U-6 ZINC U-6 U-7 ZINC U-7 U-8 ZINC U-8
C-8 ZINC C-8	U-6 ZINC U-6 U-7 ZINC U-7 U-8 ZINC U-8
C-9 ZINC C-9	U-9 ZINC U-9
C-15 ZINC CH-30	U-30
CH-31	UH-31
CH-10 ZINC CH-10.2 ZINC	UH-10 ZINC UH-11 ZINC
CH-10.3 ZINC	UH-10.3 ZINC

CIERRES	UÑAS
CH-21 ZINC	UH-13 ZINC UH-12 ZINC
CH-14 ZINC CH-15 ZINC	UH-15 ZINC UH-14 ZINC
CH-20 ZINC	UH-20.2 ZINC UH-20 ZINC
CH-8 CH-3	UH-3/8"
CH-32 ZINC	UH-32 ZINC
CH-35 ZINC	UH-35 ZINC
CH-4	UH-4

HEMBRAS	MACHOS
CB-1	UB-1
CR-1	H-5
CR-2	H-10
CR-5	H-5
CR-6	H-10
CR-6 ALU	H-16 ALU
CRH-6	HH-10
H-1	M-2
H-10	M-5
H-13	M-6 ; M-8
H-15	M-5
H-16 ZINC	M-3
H-2	M-3
H-3	M-4
H-40	M-40
H-41	M-41 ZINC
H-5	M-1
H-5G	M-1
H-6	M-6
H-7	M-8
H-7	M-8 G